

## TABELA RESUMIDA DE CONVERSÃO DE POLEGADAS EM MILÍMETROS

polegada	milímetro		
1/64"	0,3969		
1/32"	0,7938		
3/64"	1,1906		
1/16"	1,5875		
5/64"	1,9844		
3/32"	2,3813		
7/64"	2,7781		
1/8"	3,1750		
9/64"	3,5719		
5/32"	3,9688		
11/64"	4,3656		
<b>3/16"</b>	<b>4,7625</b>		
13/64"	5,1594		
7/32"	5,5563		
15/64"	5,9531		
<b>1/4"</b>	<b>6,3500</b>		
17/64"	6,7469		
9/32"	7,1438		
19/64"	7,5406		
<b>5/16"</b>	<b>7,9375</b>		
21/64"	8,3344		
11/32"	8,7313		
23/64"	9,1281		
<b>3/8"</b>	<b>9,5250</b>		
25/64"	9,9219		
13/32"	10,3188		
27/64"	10,7156		
7/16"	11,1125		
29/64"	11,5094		
15/32"	11,9063		
31/64"	12,3031		
<b>1/2"</b>	<b>12,7000</b>		
33/64"	13,0969		
17/32"	13,4938		
35/64"	13,8906		
9/16"	14,2875		
37/64"	14,6844		
19/32"	15,0813		
39/64"	15,4781		
<b>5/8"</b>	<b>15,8750</b>		
41/64"	16,2719	29/32"	23,0188
21/32"	16,6688	59/64"	23,4156
43/64"	17,0656	15/16"	23,8125
11/16"	17,4625	61/64"	24,2094
45/64"	17,8594	31/32"	24,6063
23/32"	18,2563	63/64"	25,0031
47/64"	18,6531	<b>1"</b>	<b>25,4000</b>
<b>3/4"</b>	<b>19,0500</b>	<b>1 1/4"</b>	<b>31,7500</b>
49/64"	19,4469	<b>1 1/2"</b>	<b>38,1000</b>
25/32"	19,8438	<b>2"</b>	<b>50,8000</b>
51/64"	20,2406	<b>2 1/2"</b>	<b>63,5000</b>
13/16"	20,6375	<b>3"</b>	<b>76,2000</b>
53/64"	21,0344	<b>3 1/2"</b>	<b>88,9000</b>
27/32"	21,4313	<b>4"</b>	<b>101,6000</b>
55/64"	21,8281	<b>4 1/2"</b>	<b>114,3000</b>
<b>7/8"</b>	<b>22,2250</b>	<b>5"</b>	<b>127,000</b>

